

<b>Applicant:</b> Universidad Central Del Caribe, Inc.	<b>Damage Inventory:</b> 305240	<b>Category:</b> E
<b>WO #</b> 46525 <b>FIPS#</b> 021-UNUGB-00	<b>Date:</b> 09/04-17/2019 <b>GPS:</b> 18.365953, -66.153767	
<b>Inspector:</b> Gregory Sondergeld / Alexander Nieves	<b>Damage Facility:</b> Main Building	

Damage Description:	Item #:	Damage Description:	Item #:
			10
<b>Additional Comments:</b>		Lighting, Parking lot luminaire, roof-mounted, single, 240/277-Volt, 400-Watt, metal halide bulbs, broken components caused by wind-blown debris (Main Bldg., Exterior, Wall)	
		<b>Additional Comments:</b>	

Put Photo Here



Damage Description:	Item #:	Damage Description:	Item #:
<b>Additional Comments:</b>		<b>Additional Comments:</b>	

Put Photo Here

Put Photo Here