

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 1
Roof, BUR asphaltic membrane, 3-ply, with rigid insulation and silver oxide coating, deformed, caused by wind-driven rain (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 2
Roof, Flashing, Parapet North Wall, deformed, caused by wind-driven rain (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 3
Roof, Flashing, Parapet Wall Perimeter, deformed, caused by wind-driven rain (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 4
Roof, Flashing, Parapet Wall Cap, deformed, caused by wind-driven rain (Main Bldg., Roof)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 5	Damage Description:	Item #: 6
Air Conditioning, 15 Ton Package Unit, blown covers, caused by high winds (Main Bldg., Roof)		Air Conditioning, 15 Ton Package Unit, broken condenser fins, enclosure deformed, caused by wind-blown debris (Main Bldg., Roof)	
Additional Comments: Water infiltrated to the A/C ducts through the space created by blown covers Model # TCD180F400BA Serial # 120210113D		Additional Comments: Model # TTA180E400AA Serial # 14073LONTA	



Damage Description:	Item #: 7 Roof,	Damage Description:	Item #: 8
Flashing, Parapet South Wall, deformed, caused by wind-driven rain (Main Bldg., Roof)		Exhaust Fan, 2 FT Dia, Kitchen Area, electrical issues, caused by high winds (Main Bldg., Roof)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #:	9
Exhaust Fan, 2 FT Dia. Exhaust pipe, Morgue Area, broken components, caused by high winds (Main Bldg., Roof)		
Additional Comments:		

Damage Description:	Item #:	10
Exhaust Fan, 1 FT Dia. with Motor, Laboratory Area, broken components, caused by high winds (Main Bldg., Roof)		
Additional Comments:		



Damage Description:	Item #:	11
Exhaust, 18 IN Dia, head of exhaust fan, missing components, caused by high winds (Main Bldg., Roof)		
Additional Comments:		

Damage Description:	Item #:	12
Air Extractor Grille, 24 IN x 36 IN, Stairs Area, broken components, caused by high winds (Main Bldg., Roof)		
Additional Comments:		



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019	GPS: 18.365953, -66.153767
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 13
Exhaust, 18 IN Dia, head of exhaust fan, missing components, caused by high winds (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 14
Roof, PVC roofing membrane, 2-ply, 45-mil, polyethylene thermoplastic elastomeric, hot-air seam welded with field-fasteners, deformed, caused by wind-driven rainwater intrusion (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 15
Air Conditioning, 15 Ton Package Unit, blown covers, caused by high winds (Main Bldg., Roof)	
Additional Comments: Water infiltrated to the A/C ducts through the space created by blown covers Model # TCD180E400BA Serial # 102710308D	



Damage Description:	Item #: 16
Conditioning, 10-Ton Package Unit, broken components, completely damaged, caused by high winds (Main Bldg., Roof)	
Additional Comments: Shown in the photo is the replaced unit Model XP120C00Y4A1BAA1A1 Serial # N1F9013862	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	


Damage Description:	Item #: 17
Ceiling, drywall paint, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R181)	
Additional Comments:	

Damage Description:	Item #: 18
Ceiling, drywall, repair, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R181)	
Additional Comments:	



Damage Description:	Item #: 19
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R181)	
Additional Comments:	

Damage Description:	Item #: 20
Floor, Linoleum, commercial-grade , dislodged, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R181)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 21
Base Lining, vinyl, 4 IN, dislodged, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R181)	
Additional Comments:	



Damage Description:	Item #: 22
Ceiling, 2 FT x 2 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R133)	
Additional Comments:	




Damage Description:	Item #: 23
Floor, Linoleum, commercial-grade, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R133)	
Additional Comments:	





Damage Description:	Item #: 24
Base Lining, vinyl, 4 IN, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R133)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 25	Damage Description:	Item #: 26
NOT USE		Fire Alarm System , Duct smoke detectors at Pharmacology and Microbiology Dpt., Ceiling smoke detectors at second floor service hallway	
Additional Comments:		Additional Comments:	
Put Photo Here			

Damage Description:	Item #: 27	Damage Description:	Item #: 28
Window, Alum. window frames, Exterior perimeter caulking/sealing only, peeling paint, caused by high winds (Main Bldg., Floor 2, Office R135)		Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Office R138)	
Additional Comments:		Additional Comments:	
			

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 29	Damage Description:	Item #: 30
VCT, 12x12 IN, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Hallway)		Base Lining, vinyl, 4 IN, dislodged, caused by rainwater intrusion (Main Bldg., Floor 2, Hallway)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 31	Damage Description:	Item #: 32
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Office R141)		Ceiling, 2 FT x 4 FT acoustic tile, suspended with grid, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Office)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 33
Floor, VCT, 12x12 IN, detached, caused by surface water flooding (Main Bldg., Floor 2, Hallway R291)	
Additional Comments:	

Damage Description:	Item #: 34
Base Lining, vinyl, 4 IN, detached, caused by surface water flooding (Main Bldg., Floor 2, Hallway R291)	
Additional Comments:	



Damage Description:	Item #: 35
Ceiling, drywall, repair, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Hallway R291)	
Additional Comments:	

Damage Description:	Item #: 37
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by wind-driven rain (Main Bldg., Floor 2, Laboratory R143)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 38
Light, fluorescent, recessed Troffer, broken components, caused by wind-driven rain (Main Bldg., Floor 2, Laboratory R143)	
Additional Comments:	

Damage Description:	Item #: 39
Floor, Linoleum, commercial-grade, detached, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R143)	
Additional Comments:	



Damage Description:	Item #: 40
Base Lining, vinyl, 4 IN, detached, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R143)	
Additional Comments:	

Damage Description:	Item #: 41
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by wind-driven rain (Main Bldg., Floor 2, Laboratory R144)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019	GPS: 18.365953, -66.153767
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 42	Damage Description:	Item #: 44
Floor, Linoleum, commercial-grade, detached, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R144)		Ceiling, drywall, repair and paint, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R144)	
Additional Comments:		Additional Comments:	




Damage Description:	Item #: 45	Damage Description:	Item #: 46
Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R144)		Wall, drywall, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R144)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019	GPS: 18.365953, -66.153767
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 47	Damage Description:	Item #: 48
Wall, ¼ IN thick plaster on concrete, painted, with spalls, peeling paint, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R541)		Floor, Linoleum, commercial-grade, detached, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R541)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 49	Damage Description:	Item #: 50
Base Lining, vinyl, 4 IN, detached, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R541)		Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Kitchen 145)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	


Damage Description:	Item #: 51
Wall, drywall, repair and paint , discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Kitchen 145)	
Additional Comments:	

Damage Description:	Item #: 53
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Office)	
Additional Comments:	



Damage Description:	Item #: 54
Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R147)	
Additional Comments:	

Damage Description:	Item #: 55
Ceiling, 2 FT x 2 FT acoustic tile, suspended with grid, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R147)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 56
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R147)	
Additional Comments:	

Damage Description:	Item #: 57
Wall, drywall and concrete joint, repair, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R146)	
Additional Comments:	



Damage Description:	Item #: 58
Ceiling, drywall, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R146)	
Additional Comments:	

Damage Description:	Item #: 59
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R146)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 60
Bird spike strips, perching deterrents, 6 IN H, broken components, caused by high winds (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 61
Acrylic Skylight Domes, 3 FT W x 8 FT L x 1 FT H, cracked, caused by wind-blown debris (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 62
Rooftop Air Extractor, 2 FT Dia., alum. dome cover with 1/2-HP motor, broken components, caused by high winds (Main Bldg., Roof)	
Additional Comments:	



Damage Description:	Item #: 63
Air Conditioning, 7.5 Ton Package Unit, broken components, completely damaged, caused by high winds (Main Bldg., Roof)	
<u>This unit was included in a Cat B project.</u>	
Additional Comments: Shown in the photo is the replaced unit Model # TTA090G400AA Serial # 172435YTYA	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 64	Damage Description:	Item #: 65
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Office R119)		Light, fluorescent, recessed Troffer, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Office R119)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 66	Damage Description:	Item #: 67
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Office R119)		Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by high winds (Main Bldg., Floor 2, Office R119)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 68
Window, Window frame, aluminum, dislodged, caused by high winds (Main Bldg., Floor 2, Laboratory R122)	
Additional Comments:	



Damage Description:	Item #: 69
Window, Vertical Window Blind, 3.5 IN blades, deformed, caused by high winds (Main Bldg., Floor 2, Laboratory R122)	
Additional Comments:	



Damage Description:	Item #: 70
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by wind-driven rain (Main Bldg., Floor 2, Laboratory R122)	
Additional Comments:	



Damage Description:	Item #: 71
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R122)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 72
Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R122)	
Additional Comments:	



Damage Description:	Item #: 74
Ceiling, 2 FT x 4 FT acoustic tile, suspended, broken components, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R120)	
Additional Comments:	



Damage Description:	Item #: 75
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R120)	
Additional Comments:	



Damage Description:	Item #: 76
Floor, VCT, 12x12 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Hallway)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 77
Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Hallway)	
Additional Comments:	

Damage Description:	Item #: 78
Floor, VCT, 12x12 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Storage Room R121)	
Additional Comments:	



Damage Description:	Item #: 79
Base Lining, vinyl, 4 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Storage Room R121)	
Additional Comments:	

Damage Description:	Item #: 80
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Storage Room R121)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	


Damage Description:	Item #: 81
Ceiling, 2 FT x 4 FT acoustic tile, suspended, dislodged, caused by rainwater intrusion (Main Bldg., Floor 2, Entire Floor)	
Additional Comments:	



Damage Description:	Item #: 82
Ceiling, 2 FT x 4 FT acoustic tile, suspended with grid, broken components, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R386)	
Additional Comments:	



Damage Description:	Item #: 83
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R386)	
Additional Comments:	



Damage Description:	Item #: 84
Fixed Laboratory Equipment, Metal Exhaust Fume Hood, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R386)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 85	Damage Description:	Item #: 86
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R386)		Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R386)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 87	Damage Description:	Item #: 88
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R386)		Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by wind-driven rain (Main Bldg., Floor 2, Laboratory R111)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 89
Wall, ¼ IN thick plaster on concrete, painted, torn with bubbles, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R111)	
Additional Comments:	



Damage Description:	Item #: 90
Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R111)	
Additional Comments:	



Damage Description:	Item #: 91
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R111)	
Additional Comments:	




Damage Description:	Item #: 92
Light, florescent, recessed Troffer, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R111)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019	GPS: 18.365953, -66.153767
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #:	Enter #	Damage Description:	Item #:	108
Additional Comments:			Window, Glass, 3/16-IN thick, single-glazed, tinted, broken components, caused by wind blow debris (Main Bldg., Floor 2, Classroom R113)	Additional Comments:	



Damage Description:	Item #:	109	Damage Description:	Item #:	110
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R113)	Additional Comments:		Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R113)	Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 111
Air Conditioning, A/C Ductwork, 16 IN Dia, round, galv. mounting flange only, broken components, caused by high winds (Main Bldg., Floor 2, Classroom R113)	
Additional Comments:	

Damage Description:	Item #: 112
Ceiling, 2 FT x 4 FT acoustic tile, suspended, grid only, broken components, caused by wind-blown debris (Main Bldg., Floor 2, Classroom R113)	
Additional Comments:	



Damage Description:	Item #: 113
Base Lining, vinyl, 4 IN, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R113)	
Additional Comments:	

Damage Description:	Item #: 114
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R115)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 115	Damage Description:	Item #: 116
Ceiling, 2 FT x 4 FT acoustic tile, suspended, with grid, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R115)		Light, fluorescent, recessed Troffer, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Classroom R115)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 117	Damage Description:	Item #: 118
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R167)		Ceiling, 2 FT x 4 FT acoustic tile, suspended, grid only, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R167)	
Additional Comments:		Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	


Damage Description:	Item #: 119
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R173)	
Additional Comments:	



Damage Description:	Item #: 120
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R173)	
Additional Comments:	



Damage Description:	Item #: 121
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R167)	
Additional Comments:	



Damage Description:	Item #: 122
Base Lining, vinyl, 4 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R167)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 123
Base Lining, vinyl, 4 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R173)	
Additional Comments:	



Damage Description:	Item #: 124
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R174)	
Additional Comments:	



Damage Description:	Item #: 125
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R174)	
Additional Comments:	



Damage Description:	Item #: 126
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R174)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 127
Base Lining, vinyl, 4 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R174)	
Additional Comments:	

Damage Description:	Item #: 128
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R171)	
Additional Comments:	




Damage Description:	Item #: 129
Wall, ¼ IN thick plaster on concrete, painted, with spalls, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R171)	
Additional Comments:	

Damage Description:	Item #: 131
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R171)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 132	Damage Description:	Item #: 133
Base Lining, vinyl, 4 IN, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R171)		Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R168)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 134	Damage Description:	Item #: 135
Ceiling, 2 FT x 4 FT acoustic tile, suspended, grid only, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R168)		Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R168)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 136
Base Lining, vinyl, 4 IN, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R168)	
Additional Comments:	



Damage Description:	Item #: 137
Door, Wood, with 24 IN x 30 IN vision lite, deformed, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R168)	
Additional Comments:	



Damage Description:	Item #: 138
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R151)	
Additional Comments:	



Damage Description:	Item #: 139
Ceiling, 2 FT x 4 FT acoustic tile, suspended, grid only, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R151)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 140
Wall, ¼ IN thick plaster on concrete, painted, peeling paint, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R151)	
Additional Comments:	

Damage Description:	Item #: 141
Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R151)	
Additional Comments:	



Damage Description:	Item #: 142
Ceiling, 2 FT x 4 FT acoustic tile, suspended, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R150)	
Additional Comments:	

Damage Description:	Item #: 143
Light, fluorescent, recessed Troffer, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R150)	
Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	


Damage Description:	Item #: 144
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory 499)	
Additional Comments:	



Damage Description:	Item #: 145
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R162)	
Additional Comments:	



Damage Description:	Item #: 146
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R499)	
Additional Comments:	




Damage Description:	Item #: 147
Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R499)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 148
Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Laboratory 162)	
Additional Comments:	



Damage Description:	Item #: 149
Base Lining, vinyl, 4 IN, deformed, caused by surface water flooding (Main Bldg., Floor 2, Dining Room R149)	
Additional Comments:	



Damage Description:	Item #: 150
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R161)	
Additional Comments:	



Damage Description:	Item #: 151
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, electrical issues, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R161)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 152
Wall, ¼ IN thick plaster on concrete, painted, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R161)	
Additional Comments:	

Damage Description:	Item #: 153
Wall, Concrete wall, repair, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R161)	
Additional Comments:	



Damage Description:	Item #: 154
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R159)	
Additional Comments:	

Damage Description:	Item #: 155
Ceiling, 2 FT x 4 FT acoustic tile, suspended, grid only, dislodged, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R159)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 156
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R159)	
Additional Comments:	

Damage Description:	Item #: 157
Wall, Concrete wall, clean/sanitize/repaint, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R159)	
Additional Comments:	



Damage Description:	Item #: 158
Ceiling, 2 FT x 4 FT acoustic tile, suspended, cracked, caused by rainwater intrusion (Main Bldg., Floor 2, Hallway Lobby, Bio-Chemistry)	
Additional Comments:	

Damage Description:	Item #: 159
Light, Fluorescent, recessed Troffer, acrylic lens cover only, prismatic, discolored, caused by rainwater intrusion (Main Bldg., Floor 2, Hallway Lobby, Bio-Chemistry)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305240	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.365953, -66.153767	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg.	

Damage Description:	Item #: 160
Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rainwater intrusion (Main Bldg., Floor 2, Laboratory R175)	
Additional Comments:	

Damage Description:	Item #: 161
Floor, Linoleum, commercial-grade, dislodged, caused by surface water flooding (Main Bldg., Floor 2, Laboratory R175)	
Additional Comments:	



Damage Description:	Item #:	Enter #
Additional Comments:		

Damage Description:	Item #:	Enter #
Additional Comments:		

