

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305244	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.366101, -66.154301	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg. Annex	

Damage Description:	Item #: 93	Damage Description:	Item #: 93
Wall, drywall, repair, deformed, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R484)		Wall, drywall, repair, deformed, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R484)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 95	Damage Description:	Item #: 96
Window, Wood Trim, 1/2 IN x 3 IN, discolored, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R484)		Window, Alum. window frames, perimeter caulking/sealing only, cracked, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R484)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305244	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.366101, -66.154301	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg. Annex	

Damage Description:	Item #: 97	Damage Description:	Item #: 99
Base Lining, vinyl, 4 IN, deformed, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R484)		Wall, drywall, repair, cracked, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R485)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 101	Damage Description:	Item #: 102
Base Lining, vinyl, 4 IN, deformed, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R485)		Ceiling, drywall, repair, discolored, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R483)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305244	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.366101, -66.154301	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg. Annex	

Damage Description:	Item #: 103
Wall, drywall, painted, discolored, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Office R483)	
Additional Comments:	



Damage Description:	Item #: 104
Wall, drywall, repair, cracked, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Classroom R480)	
Additional Comments:	



Damage Description:	Item #: 105
Wall, drywall, painted, cracked, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Classroom R480)	
Additional Comments:	





Damage Description:	Item #: 106
Base Lining, vinyl, 4 IN, dislodged, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Dining Room R480)	
Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305244	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.366101, -66.154301	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Main Bldg. Annex	

Damage Description:	Item #: 107	Damage Description:	Item #:
Floor, carpet, commercial-grade, discolored, caused by rain water intrusion (Main Bldg. Annex, Floor 2, Dining Room R480)			
Additional Comments:		Additional Comments:	



Damage Description:	Item #:	Damage Description:	Item #:
Additional Comments:		Additional Comments:	

