

Applicant: Universidad Central del Caribe	Damage Inventory # 305244	Category E
Work Order # 62056 FIPS # 021-UNUGB-00	Date: July 17, 2020	GPS 18.36610, -66.15430
Site Inspector: Edwin G. Rosario	Damage Facility: Main Building Annex	

Damage Description: Photo# 1
North Elevation



Damage Description Photo# 2
West Elevation







Damage Description: Photo# 3
South Elevation



Damage Description Photo# 4
East Elevation




Applicant: Universidad Central del Caribe		Damage Inventory # 305244		Category E	
Work Order# 62056		FIPS # 021-UNUGB-00		Date: July 17, 2020	
				GPS 18.36610, -66.15430	
Site Inspector: Edwin G. Rosario			Damage Facility: Main Building Annex		
			Photo# 5		
Exterior, Concrete wall, concrete spalling, caused by wind driven rain and water saturation			Damage Description		Photo# 6
			Exterior, Concrete wall, discolored paint, caused by wind driven rain.		
Damage Description:			Photo# 7		
Exterior, Aluminum window, caulking around damaged by wind driven rain			Damage Description		Photo# 8
			Exterior, Metal frame canopy (North and South), fabric covering, broken by high winds (Photo shows the canopy at South side already replaced)		

Applicant: Universidad Central del Caribe		Damage Inventory # 305244		Category E	
Work Order # 62056		FIPS # 021-UNUGB-00		Date: July 17, 2020	
				GPS 18.36610, -66.15430	
Site Inspector: Edwin G. Rosario		Damage Facility: Main Building Annex			
		Photo# 9		Photo# 10	
Interior, Room # 480, Wall, drywall cracked caused by rain water intrusion		Interior, Room # 480, Wall, drywall painted, discolored, caused by rain water intrusion			
					
Damage Description:		Photo# 11		Photo# 12	
Interior, Room # 580, Base molding, vinyl, 4 IN, dislodged, caused by rain water intrusion		Interior, Room # 580, Carpet, Commercial grade, discolored, caused by rain water intrusion			
					

Applicant: Universidad Central del Caribe		Damage Inventory # 305244	Category E
Work Order # 62056	FIPS # 021-UNUGB-00	Date: July 17, 2020	GPS 18.36610, -66.15430
Site Inspector: Edwin G. Rosario		Damage Facility: Main Building Annex	

Damage Description:	Photo# 13
Interior, Hallway, Aluminum window, broken components, caused by high winds	
	

Damage Description	Photo# 14
Interior, Room # 483, Wall, drywall painted, discolored, caused by rain water intrusion	
	

Damage Description:	Photo# 15
Interior, Room # 483, Wall, drywall, painted, discolored caused by rain water intrusion	
	


Damage Description	Photo# 16
Interior, Room # 484, Wall, drywall, deformed caused by rain water intrusion	
	

Applicant: Universidad Central del Caribe	Damage Inventory # 305244	Category E
Work Order # 62056 FIPS # 021-UNUGB-00	Date: July 17, 2020	GPS 18.36610, -66.15430
Site Inspector: Edwin G. Rosario	Damage Facility: Main Building Annex	

Damage Description:	Photo# 17
Interior, Room # 484, Wall, drywall, peeling paint, caused by rain water intrusion	
	

Damage Description	Photo# 18
Interior, Room # 484, Window, wooden casing trim, pine, discolored, caused by rain water intrusion	
	

Damage Description:	Photo# 19
Interior, Room # 484, Window, aluminum frame, caulking sealing, cracked, caused by rain water intrusion	
	

Damage Description	Photo# 20
Interior, Room # 484, Base molding, vinyl, deformed caused by rain water intrusion	
	

Applicant: Universidad Central del Caribe	Damage Inventory # 305244	Category E
Work Order# 62056 FIPS # 021-UNUGB-00	Date: July 17, 2020	GPS 18.36610, -66.15430
Site Inspector: Edwin G. Rosario	Damage Facility: Main Building Annex	

Damage Description: Interior, Room # 484, Floor, Carpet, commercial grade, discolored, caused by rain water intrusion (Photo shows already replaced carpet)

Photo# 21




Damage Description Interior, Room # 485, Wall, drywall, cracked, caused by rain water intrusion

Photo# 22




Damage Description: Interior, Room # 485, Wall, drywall, painted, discolored, caused by rain water intrusion

Photo# 23



Damage Description Interior, Room # 485, Base molding, vinyl, deformed, caused by rain water intrusion

Photo# 24



Applicant: Universidad Central del Caribe		Damage Inventory # 305244	Category E
Work Order # 62056	FIPS # 021-UNUGB-00	Date: July 17, 2020	GPS 18.36610, -66.15430
Site Inspector: Edwin G. Rosario		Damage Facility: Main Building Annex	

Damage Description:	Photo#
N/A	

Damage Description	Photo#
N/A	

Damage Description:	Photo#
N/A	

Damage Description	Photo#
N/A	