

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305310	Category: G
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.36519, -66.152814	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Site 1	

Damage Description:	Item #: 1	Damage Description:	Item #: 2
Concrete sidewalk, panels, 4 IN Thick, cracked, caused by other (Site 1)		Sidewalk trim tiles, Terracotta clay, 4 IN x 8 IN, cracked, caused by other (Site 1)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 3 Storm	Damage Description:	Item #: 4
drainage system, Casa Salud Courtyard area, clogged, caused by surface water flooding (Site 1)		Aggregate concrete bench, 48 IN L x 18 IN W x 3 IN D, cracked, caused by wind-blown debris (Site 1)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305310	Category: G
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.36519, -66.152814	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Site 1	

Damage Description:	Item #:	5
Generator Shed luminaire, single, 110-Volt, 80-Watt, high-pressure sodium bulb, including rewiring from pole-to-fixture only, mounted onto existing 25-FT tapered, aluminum light pole, missing components, caused by high winds (Site 1)		
Additional Comments:		

Damage Description:	Item #:	6
Security fencing, commercial-grade, chain link, 9-gauge, 4 FT tall, located around perimeter of propane tanks at Generator Shed, deformed, caused by wind-blown debris (Site 1)		
Additional Comments:		



Damage Description:	Item #:	7
Guard rail, galvanized steel piping, 1 1/2 IN dia., triple rail, painted finish, peeling paint, caused by wind-driven rain (Site 1)		
Additional Comments:		

Damage Description:	Item #:	8
Facility identification sign, aluminum, 3 FT x 6 FT, missing components, caused by high winds (Site 1)		
Additional Comments:		



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305310	Category: G
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.36519, -66.152814	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Site 1	

Damage Description:	Item #: 9	Damage Description:	Item #: 10
One-way travel sign, aluminum, 12 IN x 18 IN, missing components, caused by wind blow debris (Site 1)		Lighting, Parking lot luminaire, roof-mounted, single, 240/277-Volt, 400-Watt, metal halide bulbs, broken components, caused by wind-blown debris (Main Bldg. , Exterior, Wall)	
Additional Comments:		Additional Comments:	



Damage Description:	Item #: 11	Damage Description:	Item #: 12
Parking lot luminaire, single, 240/277-Volt, 400-Watt, metal halide bulbs, including pole-to-fixture rewiring only, mounted on existing 35 FT steel light pole, missing components, caused by wind-blown debris		Facility identification sign, aluminum, 2 FT x 4 FT, missing components, caused by wind-blown debris (Site 1)	
Additional Comments:		Additional Comments:	



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305310	Category: G
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04-17/2019 GPS: 18.36519, -66.152814	
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Site 1	

Damage Description:	Item #: 13
Engineered embankment, slope erosion, soil renourishment and repair, erosion, caused by wind-driven rain and surface flooding (Site 1)	
Additional Comments:	



Damage Description:	Item #: 15
Engineered embankment, slope erosion, soil renourishment and repair, cracked, caused by surface water flooding (Site 1)	
Additional Comments:	



Damage Description:	Item #: 14
Asphalt parking lot, cracked, caused by surface water flooding (Site 1)	
Additional Comments:	



Damage Description:	Item #: 21
Facility identification sign, aluminum, 2-section, 5 FT W x 6 FT H, broken components, caused by high winds (Site 1)	
Additional Comments:	

