

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Downspout, commercial-grade, seamless, aluminum, 5 IN, missing components, caused by high winds (Neuroscience Bldg., Roof)	Item #: 17	Damage Description: Wall, 1/4 IN thick plaster on concrete, painted, discolored, caused by wind driven rain (Neuroscience Bldg., Floor 1, Exterior Rear)	Item #: 18
Additional Comments:		Additional Comments:	





Damage Description: Roof, BUR membrane, 4-ply, with protective silver oxide coating, cracked, caused by rain water intrusion (Neuroscience Bldg., Roof)	Item #: 19	Damage Description: Roof, Metal roof, ribbed, with sprayed polyurethane foam (SPF) insulation overlay and protective aliphatic acrylic polyurethane seal coating, deformed, caused by high winds (Neuroscience Bldg., Roof)	Item #: 20
Additional Comments:		Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525 FIPS# 021-UNUGB-00	Date: 09/04/17/2019	GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: <input type="text"/> Item #: <input type="text"/> 16	Damage Description: <input type="text"/> Item #: <input type="text"/> Enter #
Gutter, commercial-grade, seamless, aluminum, 5 IN, broken components, caused by high winds (Neuroscience Bldg., Roof)	
Additional Comments:	
	
Put Photo Here	

Damage Description: <input type="text"/> Item #: <input type="text"/> Enter #	Damage Description: <input type="text"/> Item #: <input type="text"/> Enter #
Additional Comments:	
	
Put Photo Here	

Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Wall, 1/4 IN thick plaster on concrete, repair spalling, cracked, caused by wind driven rain (Neuroscience Bldg., Entire Building)	Item #: 49	Damage Description: 1/4 IN thick plaster on concrete, painted, peeling paint, caused by wind driven rain (Neuroscience Bldg., Entire Building)	Item #: 50 Wall,
Additional Comments:	Additional Comments:		



Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R514)	Item #: 51	Damage Description: Base Lining, vinyl, 4 IN, detached, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office)	Item #: 52
Additional Comments:	Additional Comments:		



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R516)	Item #: 53	Damage Description: Base Lining, vinyl, 4 IN, detached, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R516)	Item #: 54
Additional Comments:	Additional Comments:		



Damage Description: Base Lining, vinyl, 4 IN, detached, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office)	Item #: 55	Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R518)	Item #: 56
Additional Comments:	Additional Comments:		



Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Hallway)	Item #: 57	Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Laboratory)	Item #: 58
Additional Comments:		Additional Comments:	




Damage Description: Wall, 1/4 IN thick plaster on concrete, repair spalling, cracked, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Laboratory)	Item #: 59	Damage Description: Wall, 1/4 IN thick plaster on concrete, painted, discolored, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Laboratory)	Item #: 60
Additional Comments:		Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Floor, ceramic tile, 16x16 IN, thin set, stained, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Laboratory)	Item #: 61	Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Laboratory R526)	Item #: 62
Additional Comments:		Additional Comments:	




Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Hallway)	Item #: 63	Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Conference R524)	Item #: 64
Additional Comments:		Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R511)	Item #: 65	Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office)	Item #: 66
Additional Comments:		Additional Comments:	




Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Hallway)	Item #: 67	Damage Description: Base Lining, vinyl, 4 IN, detached, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Hallway)	Item #: 68
Additional Comments:		Additional Comments:	




Applicant: Universidad Central Del Caribe, Inc.	Damage Inventory: 305290	Category: E
WO # 46525	FIPS# 021-UNUGB-00	Date: 09/04/17/2019 GPS: 18.371576, -66.153119
Inspector: Gregory Sondergeld / Alexander Nieves	Damage Facility: Neuroscience Bldg.	

Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office)	Item #: 69	Damage Description: Light, fluorescent, recessed Troffer, electrical issues, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office)	Item #: 70
Additional Comments:		Additional Comments:	
			

Damage Description: Ceiling, 2 FT x 4 FT acoustic tile, suspended, deformed, caused by rain water intrusion (Neuroscience Bldg., Floor 1, Office R522)	Item #: 72	Damage Description:	Item #: Enter #
Additional Comments:		Additional Comments:	
		Put Photo Here	