

UNIVERSIDAD CENTRAL DEL CARIBE


RAIN WATER FLOW



1. Courtyard: Affected by run-off water coming from Calle España.
2. Parking lot: Affected by run-off water coming from Calle España and hills between Calle España and parking lot.
3. Food court: Affected by run-off water coming from Calle España.

Slope Analysis

- Slope from hills to parking lot



- Slope from street to food court and courtyard.

